## **EAST Search History**

## **EAST Search History (Prior Art)**

Ref#	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S101	5681	glass with thickness with pressure	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/08/25 13:54
S102	222	glass with thickness with pressure with cut\$4	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/08/25 13:55
S103	757	glass with sensor with cut\$4	US-PGPUB; USPAT	OR	ON	2010/08/25 18:40
S104	186	glass with measur\$4 with thick\$4 with cut\$4	US-PGPUB; USPAT	OR	ON	2010/08/25 18:40
S105	196	glass with measur\$4 with thick\$4 with (cut\$4 or scor\$4)	US-PGPUB; USPAT	OR	ON	2010/08/25 18:50
S106	51	glass with (sens\$4 or detect\$4) with thick\$4 with (cut\$4 or scor\$4)	US-PGPUB; USPAT	OR	ON	2010/08/25 22:48
S107	73	glass with (sens\$4 or detect\$4) with thick\$4 with (cut\$4 or scor\$4)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/08/25 22:48
S108	81243	ota.inv.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/08/26 07:32

S109	3526	ota.inv. and glass	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/08/26 07:32
S110	100	: §	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/08/26 07:33

## 8/26/2010 10:16:47 AM

C:\ Documents and Settings\ PNguyen10\ My Documents\ EAST\ Workspaces \ 10,523,850-Method for cutting a continuous glass sheet during the production of flat glass.wsp